

Service Bulletin

Product : Next8
 Bulletin # : CNZ202000130-02
 CNZ202000132-02
 Release Date :2020.05.23

[Subject] Next8 Gen 2.5 Ice maker and DC valve change



Bulletin Type: Quality ☐ Parts ☒ Others ☐

Applicable only with symptoms ☒ with every repair ☐

Applicable for Serial Number : After 005TR*~ (After 20200523)

Applicable for models


Model(ECN)	Factory Model/Suffix
GF-L570PL	GC-L22FTLPL.APZRGAP
GF-L570MBL	GC-L22FTQPL.AMCRGAP
GF-V570MBL	GC-X22FTQKL.AMCRGAP

Symptoms	- Ice maker Gen2.0→Gen 2.5, - water valve AC→ DC	Picture	Ice Maker Assembly, Kit Gen 2.0(IR Type)  ➔ Gen 2.5(Lever Type) 
Cause	- Global standardization		Water Valve  AC valve ➔  DC valve

Service Bulletin

Product : Next8
Bulletin # : CNZ202000130-01
CNZ202000132-01
Release Date :2020.05.23

1. Repair Instruction



Service Bulletin

Product : Next8
 Bulletin # : CNZ202000130-01
 CNZ202000132-01
 Release Date :2020.05.23

2. Current and New (Visual / Part number & Name etc)

SVC Location	Description	Part number		Remark
		As is	To be	
500A	PCB Assembly, Main	EBR85712604	EBR88758506	Bulletin #: CNZ202000130-02 GC-L22FTLPL.APZRGAP
278A	cover assembly display	ACQ88651565	ACQ91485809 ACQ91485810	
501A	PCB assembly, display	EBR84146406	EBR84146434	
231E	Door Foam Assembly, Refrigerator	ADD75796101	ADD75796105	
500C	Case Assembly, PCB	ABQ76121008	ABQ76121025	
600A	Ice Maker Assembly, Kit	AEQ73110214	AEQ73110222	
619C	Filter assembly, water	ADQ75213401	ADQ75213402	
619B	Valve, water	MJX62831302	MJX64471402	
619A	Valve assembly, water	AJU72992604	AJU75632506	

SVC Location	Description	Part number		Remark
		As is	To be	
500A	PCB Assembly, Main	EBR85712604	EBR88758506	Bulletin #: CNZ202000131-02 GC-L22FTQPL.AMCRGAP
278A	cover assembly display	ACQ88651575	ACQ91485810 ACQ91485809	
501A	PCB assembly, display	EBR84146406	EBR84146434	
231E	Door Foam Assembly, Refrigerator	ADD75796102	ADD75796106	
500C	Case Assembly, PCB	ABQ76121012	ABQ76121026	
600A	Ice Maker Assembly, Kit	AEQ73110214	AEQ73110222	
619C	Filter assembly, water	ADQ75213401	ADQ75213402	
619B	Valve, water	MJX62831302	MJX64471402	
619A	Valve assembly, water	AJU72992604	AJU75632506	

Service Bulletin

Product : Next8
Bulletin # : CNZ202000130-01
CNZ202000132-01
Release Date :2020.05.23

2. Current and New (Visual / Part number & Name etc)

SVC Location	Description	Part number		Remark
		As is	To be	
500A	PCB Assembly, Main	EBR85712631	EBR88758512	Bulletin #: CNZ202000132-02 GC-X22FTQKL.AMCRGAP
278A	cover assembly display	ACQ88651575	ACQ91485810 ACQ91485809	
501A	PCB assembly, display	EBR84146406	EBR84146434	
231E	Door Foam Assembly, Refrigerator	ADD75796102	ADD75796106	
500C	Case Assembly, PCB	ABQ76121012	ABQ76121026	
600A	Ice Maker Assembly, Kit	AEQ73110214	AEQ73110222	
619C	Filter assembly, water	ADQ75213401	ADQ75213402	
619B	Valve, water	MJX62831302	MJX64471402	
619A	Valve assembly, water	AJU72992604	AJU75632506	

Part Interchangeable :

Yes or No 로 표기

	Current Part	New Part
Current Product	Yes	No
New Product	No	Yes

Scrap Current Part in LG Warehouse: Yes

☐ No



Extended Warranty

This service is covered by an extended warranty Yes ☐ No ☒

- If Yes, Parts for () years and Labor for () years by LG.

- If No, Parts and labor are charged to the customer if outside warranty period.

- The warranty period, including any extended warranty above, starts from the original date of purchase.

- The information is available through "https://gsfs-america.lge.com" with a valid ID.
- The information is intended for experienced technicians, not for customer.
- The information is subject to change or update without notice.